



Baring Bridge #509A

Baring Bridge Emergency Action



Deficiencies found

Many floor beams have splits and cracks: Need repairs



All stringers were sounded and drilled at two different locations on the main span. More than 40% of these stringers were found very soft at top and bottom. Some have splits or crushing

All deck planks worn $\frac{1}{2}$ " to 1" deep on wheel lines and fasteners are loose