

Yarrow Point buoys to be maintained under KCSO Contract for Marine Patrol Services**Yarrow Point Buoy #1**

Type: White plastic- No Wake 8 MPH
Location: N 47*38.988 W 122*12.660
Depth: 10'
Condition: OK

Yarrow Point Buoy # 2

Type: Aluminum-Slow 8 MPH
Location: N 47*39.177 W 122*12.723
Depth: 29'
Condition: OK

Yarrow Point Buoy # 3

Type: Aluminum- No Wake Slow 8 MPH
Location: N 47*39.245 W 122*12.831
Depth: 34'
Condition: OK- Slight Mercer Island Lean

Yarrow Point Buoy # 4

Type: White Plastic- No Wake 8 MPH
Location: N 47*39.009 W 122*13.302
Depth: 39'
Condition: Cracked, needs to be replaced

Yarrow Point Buoy # 5

Type: Aluminum- No Wake 8 MPH
Location: N 47*38.775 W 122*13.412
Depth: 34'
Condition: OK

Yarrow Point Buoy # 6

Type: Aluminum- Slow 8 MPH
Location: N 47*38.625 W 122*13.436
Depth: 20'
Condition: OK

Yarrow Point Buoy # 7

Type: White Plastic Can- No Wake 8 MPH
Location: N 47*38.465 W 122*13.474
Depth: 8'
Condition: Cracked, needs to be replaced

Yarrow Point Buoy # 8

Type: Aluminum- Slow 8 MPH
Location: 47.65371N 122.21727W
Depth: 26'
Condition: Missing